Oil Field Environmental Incident Summary

Responsible Party: MARATHON OIL COMPANY **Well Operator:** MARATHON OIL COMPANY

Well Name: RECKARD SWD #1

Field Name: BAILEY Well File #: 90276

Date Incident:6/13/2014Time Incident:04:08Facility ID Number:County:DUNNTwp:146Rng:94Sec:27Qtr:

Location Description: Inside steel secondary containment area.

Submitted By: Luis Londono Received By:

Contact Person: Luis Londono

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 4500 Feet

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 15 Barrels 15 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 6/30/2014 Clean Up Concluded: 6/18/2014

Risk Evaluation:

No immediate risks were identified.

Areal Extent:

Release was contained to the steel secondary containment area. Containment area is also lined.

Potential Environmental Impacts:

No potential environmental impacts were identified. Released was contained within steel secondary containment.

Action Taken or Planned:

Defective valve was taken out of service and replaced. Standing fluid was removed via vacuum truck and disposed off at an approved disposal.

Wastes Disposal Location: Recovered fluid was disposed off at an approved disposal. Recovered

affected material within the containment will be taken to Clean Harbors

in Sawyer, ND for proper disposal.

Agencies Involved:

Updates

Date: 6/16/2014 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.